



**Garden City Fire
Department**

Station: **2**
Shifts Or Platoon: **A Shift**

Location: Tyson Fresh Meats 3105 N IBP RD Sherlock (Township of) KS 67851	Incident Type: 111 - Building fire
Lat/Long: N 37° 59' 59.7" W 101° 0' 42.11"	FDID: FI101 Incident #: 2019-563 Exposure ID: 41979806 Exposure #: 0 Incident Date: 08/09/2019
Zone: Sherlock - Sherlock Township Location Type: 1 - Street address Population Density: Urban	

Report Completed by:	Seirer , Ken A	ID: SEI01	Date: 10/13/2019
Report Reviewed by:	Seirer , Ken A	ID: SEI01	Date: 10/22/2019
Report Printed by:	Beesley, Cynthia L.	ID: BEE01	Date: 10/22/2019 Time: 10:28

Structure Type: Enclosed building	Property Use: 700 - Manufacturing, processing		
Automatic Extinguishment System Present: <input checked="" type="checkbox"/>	Detectors Present: <input type="checkbox"/> Cause of Ignition: Unintentional		
Aid Given or Received: None	Primary action taken: 11 - Extinguishment by fire service personnel		
Additional actions: 12 - Salvage & overhaul , 80 - Information, investigation & enforcement, other			
Losses	Pre-Incident Values		
Property:	Property:	Civilian Injuries: 0	Fire Service Injuries: 0
Contents:	Contents:	Civilian Fatalities: 0	Fire Service Fatalities: 0
Total:	Total:	Total Casualties: 0	Total Fire Service Casualties: 0
Total # of apparatus on call: 10		Total # of personnel on call: 28	

NARRATIVE (1)

Narrative Title: n/a

Narrative Author: Martin, Cody

Narrative Date: 08/11/2019 14:27:00

Narrative Apparatus ID: 616

Narrative:

At approximately 20:34 hours on August 9, 2019, the Garden City Fire Department was dispatched to a oil fire by the Finney County Law Enforcement Center to 3105 North IBP Road, Sherlock Township, Finney County, Kansas.

Upon arriving on scene, fire command advised engine 616 to pull an attack hose line and get it on top of the roof. Engine 621 arrived on scene and supplied water to engine 616. Fire personnel gained access to the roof and began hoisting the attack hose line up. Engine 621 established a water supply via hydrant and began relay pumping operations. Fire personnel attempted entry into the structure and due to falling objects, heavy smoke conditions, and high heat, fire personnel were forced to explore other entry points and began fire attack with master streams and aerial devices. Fire personnel relocated devices several times to try and gain better access to the fire. Fire personnel began made entry into an adjoining part of the structure to prevent further progression of the fire. Fire personnel were able to extinguish flames and begin salvage and overhaul to extinguish hot spots. All tools and equipment were recovered and all apparatus was placed back into service.

Scene turned over to business management.

FFII Cody Martin
August 11, 2019

FIRE			
Acres Burned	None or Less Than One	Acres Burn From Wildland Form	False
Material			
Meat products, including poultry & fish , Animal skins, other			
Storage Use			
Processing or manufacturing , Processing or manufacturing			
Area Of Fire Origin	Machinery room or area; elevator machinery room	Heat Source	Spark, ember, or flame from operating equipment
Item First Ignited	Liquids, piping, filters, other	Fire Is Confined To Object Of Origin	
Type Of Material	Undetermined	Cause Of Ignition	Unintentional
Factor Contributing To Ignition	Undetermined		
Human Factors Contributing	None		
Equipment Involved In Ignition Flag	True	Equipment Involved	Welding torch.
Equipment Power Source	Electrical line voltage (>= 50 volts)	Equipment Portability	Portable

STRUCTURE FIRE			
Structure Type	Enclosed building	Building Status	In normal use
# Of Stories At Above Grade	3	# Of Stories Below Grade	0
Square Feet	508000	Length	
Width		Floor Of Origin	2
Fire Spread	Confined to building of origin		
Minor Damage	0	Significant Damage	0
Heavy Damage	0	Extreme Damage	0
Presence OF AES	Present	Type Of AES	Wet-pipe sprinkler system
Operation Of Automatic Extinguishing System	Undetermined	Number Of Sprinkler Heads Operating	

PEOPLE -- PERSON 1			
Is Owner	False	Business Name	Tyson Fresh Meats
Telephone Number	309-230-0207	Involvement	Plant Manager
Name	Tony Lane	Date of Birth	
Address			

PEOPLE -- PERSON 2			
Is Owner	False	Business Name	Tyson Fresh Meats
Telephone Number		Involvement	Assistant Plant Manager
Name	Paul Finch	Date of Birth	
Address			

PEOPLE -- PERSON 3			
Is Owner	False	Business Name	Tyson Fresh Meats
Telephone Number	712-899-2781	Involvement	Senior Safety Manager
Name	Fred Braun	Date of Birth	
Address			

CUSTOM FIELDS FORM
Vehicle 1 VIN
Vehicle 1 Make, Year & Model
Vehicle 1 Insurance Info
Vehicle 2 VIN
Vehicle 2 Make, Year & Model
Vehicle 2 Insurance Info
Vehicle 3 VIN
Vehicle 3 Make, Year & Model
Vehicle 3 Insurance Info
Vehicle 4 VIN
Vehicle 4 Make, Year & Model
Vehicle 4 Insurance Info

Member Making Report (BC Ken A Seirer): _____

Incident Reviewer (BC Ken A Seirer): _____